




SIDE VIEW OF BOX



TOP VIEW OF BOX




SECTION A-A




SECTION B-B


LID FASTENERS
M3 x 10 mm Screws for FRABS/Polycarb
#4 x 1/2" Self Tapping for GPABS




EXPLODED VIEW OF ASSEMBLY




END VIEW OF ENCLOSURE





SECTION C-C



SIDE VIEW OF ASSEMBLY



SECTION D-D



29.99999

110.9997

11.6407

5.0000

75.1135

5.0000

5.0239

9.8787

111.2554

